



The Broken Railcar

The bottom of this railcar is broken, yet it holds waste that was transported from out of state. The loose waste material could easily blow out or fall out of the railcar while resting or traveling. When this photo was taken, the car was sitting in a residential area near WIN Waste Innovations' Fostoria landfill, formerly called Sunny Farms Landfill.

Photo taken January, 2024